



FIG. 1A**FIG. 1B**



FIG. 2A**FIG. 2B**


FIG. 3

FIG. 4

SELF FE \ RELATIVE FE	0	1	2	3	4	5	6	7
0	X	1	2	3	4	5	6	7
1	1	X	3	4	5	6	7	0
2	2	3	X	5	6	7	0	1
3	3	4	5	X	7	0	1	2
4	4	5	6	7	X	1	2	3
5	5	6	7	0	1	X	3	4
6	6	7	0	1	2	3	X	5
7	7	0	1	2	3	4	5	X

FIG. 5

--->

FE	Port	FE	Port	VPI
0	11	1	20	1
0	12	2	30	2
0	13	3	40	3
0	14	4	50	4
0	15	5	60	5
0	16	6	70	6
0	17	7	80	7
1	22	2	31	3
1	23	3	41	4
1	24	4	51	5
1	25	5	61	6
1	26	6	71	7
1	27	7	81	0
2	33	3	42	5
2	34	4	52	6
2	35	5	62	7
2	36	6	72	0
2	37	7	82	1
:	:	:	:	:
5	66	6	76	3
5	67	7	86	4
6	77	7	87	5


FIG. 6

FIG. 7

SELF FE \ RELATIVE FE	0	1	2	3	4	5	6	7
0	X							
1		X						
2			X					
3				X				
4					X			
5						X		
6							X	
7								X


FIG. 8


FIG. 9

FIG. 10